

# **EXHIBIT B**

19-AUG-2005 14:13 FROM SUNFIELD.COM.CN

TO 0088672240520

P.01/17

**SGS**

2/F Oastar Building, Zhongkang Road, Shangmeilin, Shenzhen, China

Tele. (86 755) 83114358

Fax: (86 755) 83114354/ 83103194

**Inspection Report**

Report Ref. No.: SZXWT00122214

To :	Tivoli Audio, LLC	Fax / E-mail:	tivolicon@aol.com
Att :	Tom Devesto		
Cc :	Sunfield Shenzhen	Fax / E-mail :	
Att :	Peter Peng		
From :	Hanson Cai	Fax / E-mail:	Hanson_cai@sgs.com
SGS File No.:	CN1US-079377	Date:10/May/2005	SGS Registration No.: CN1US-079377

Buyer: Tivoli Audio, LLC  
 Agent: N/A  
 Supplier: Sunfield, TW  
 Manufacturer: Sunfield, ShenZhen  
 Product description: Speakers

L/C Number: (x) Not Available

P.O. Number: SF0501252  
SF0501253

Service performed: FRI Inspection Date: 10 -MAY - 2005

Inspection Location: Shajing, ShenZhen

REFERENCE SAMPLE PROVIDED:

By Principal (For data measurement only)

**1.0 SUMMARY OF INSPECTION RESULT:**

Model No	Quantity for Inspection	AQL applied	Sample size	Overall result
ST1- L/R MKII	740	According to Client instruction are-using ANSI/ASQC Z1.4-1993, Single sampling plans for normal inspection AQL = Level I - according to letter code sample size only. Critical = Not allow Major = 0.65 Minor = 1.5	32	Not confirmed

Note: Inspection results are defined as "Conformed" "Not conformed" "Not applicable" and "Subject to Client's Evaluation"

**FOLLOW UP ACTIONS: (as applicable)**☐ Inspection certificate will be issued☐ Supplier advised shipment scheduled for \_\_\_\_\_Page 1 of 4  
CN-D-OPS

The Company under its General Conditions issues this report for inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than three times the amount of the fees or commission. Except by mutual arrangement, however, it drawn, will not be retained by the Company for more than 12 months.

19-AUG-2005 14:14 FROM SUNFIELD.COM.CN

TO 0088672240520

P.02/17



2/F Oastar Building, Zhongkang Road, Shangmeilin, Shenzhen, China

Tels. (86 755) 83114358

Fax: (86 755) 83114354/ 83103194

## Inspection Report

Report Ref. No.: SZXWT00122214

To :	Tivoli Audio, LLC	Fax / E-mail:	tivolicon@aol.com
Att :	Tom Devesto		
Cc :	Sunfield Shenzhen	Fax / E-mail :	
Att :	Peter Peng		
From :	Hanson Cai	Fax / E-mail:	Hanson_cai@sgs.com
SGS File No.:	CN1US-079377	Date:10/May/2005	SGS Registration No.: CN1US-079377

Buyer: Tivoli Audio, LLC

Agent: N/A

Supplier: Sunfield, TW

Manufacturer: Sunfield, Shenzhen

Product description: Speakers

L/C Number: (x) Not Available

P.O. Number: SF0501252

SF0501253

Service performed: FRI

Inspection Date: 10 -MAY - 2005

Inspection Location: ShaJing, Shenzhen

REFERENCE SAMPLE PROVIDED:

By Principal (For data measurement only)

### 1.0 SUMMARY OF INSPECTION RESULT:

Model No	Quantity for inspection	AQL applied	Sample size	Overall result
ST1-LR MKII	740	According to Client instruction are using ANSI/ASQC Z1.4-1993, Single sampling plans for normal inspection AQL = Level I - according to letter code sample size only. Critical = Not allow Major = 0.65 Minor = 1.5	32	Not confirmed

Note: Inspection results are defined as "Conformed" "Not conformed" "Not applicable" and "Subject to Client's Evaluation"

FOLLOW UP ACTIONS: (as applicable)

☐ Inspection certificate will be issued

☒ Supplier advised shipment scheduled for

Page 1 of 4  
CN-D-OPS.

The Company under its General Conditions issues this report for inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Shipments to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be returned by the Company for more than three months.

19-AUG-2005 14:14 FROM SUNFIELD.COM.CN

TO 0088672240520

P.03/17

**SGS**

- ☐ Manufacturer / supplier commented on inspection result as follow: \_\_\_\_\_
- ☐ Please instruct regarding issuance of inspection certificate.
- ☐ We sent you defective samples by \_\_\_\_\_ AWB. No.: \_\_\_\_\_ on \_\_\_\_\_. Please advise your evaluation.
- ☐ We recommend the following corrective action: \_\_\_\_\_
- ☐ Additional SGS service \_\_\_\_\_ results due by \_\_\_\_\_

**2.0 SUMMARY OF INSPECTION CONTENTS**

Model No	Style / Material / Color	Workmanship / Visual / Function	Packing	Marking / label	Data measurement
ST1-L/R MKII	Confirmed	Confirmed	Confirmed	Confirmed	Actual Finding

**3.0 WORKMANSHIP APPEARANCE / FUNCTION INSPECTION FINDINGS:**

(As according to Client's instruction "Critical and Major defect" are not allowed! And "Minor defects" are just for repair and improvement mainly!)

Model No	Defect description	Critical	Major	Minor
ST1-R MKII	Scratch mark on rear cabinet. (S/N: S13605)	0	0	1

**4.0 PACKING**

Model No	Export packing	Individual packing
ST1-L/R MKII	2 ply corrugated carton and sealed by gummed tapes	Each unit was protected with poly bag and poly foam, then packed into carton together with accessories bag (3pcs spikes, 3pcs rubber caps, 2pcs plastic foot and 4pcs black screw, user's guide and warranty card.)

**5.0 MARKING / LABELING**

Model No	On Export carton
ST1-L/R MKII	<p><b>1). Shipping mark</b></p> <p style="text-align: center;"><b>Sapphire™</b> <b>ST1 MKII</b> High performance three-way Tower Speaker</p> <p><b>2). Side mark</b></p> <p><b>HANDLE WITH CARE</b> Designed and Engineered by Cary Christie And Tom DeVesto Exclusive 1" Sapphire Polycell Dome Tweeter 5.25" Aluminum Cone Midranges 8" side-firing woofer Magnetically Shielded Bi-Wirable Bass Reflex Design</p>

Page 2 of 3  
CN-D-OPS

The Company under its General Conditions Issues this report for inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

The Company is not liable for the Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

19-AUG-2005 14:15 FROM SUNFIELD.COM.CN

TO 0088672240520

P.04/17

**SGS**

- ☐ Manufacturer / supplier commented on inspection result as follow: \_\_\_\_\_
- ☐ Please instruct regarding issuance of inspection certificate.
- ☐ We sent you defective samples by \_\_\_\_\_ AWB. No.: \_\_\_\_\_ on \_\_\_\_\_ Please advise your evaluation.
- ☐ We recommend the following corrective action: \_\_\_\_\_
- ☐ Additional SGS service \_\_\_\_\_ results due by \_\_\_\_\_

**2.0 SUMMARY OF INSPECTION CONTENTS**

Model No	Style / Material / Color	Workmanship / Visual / Function	Packing	Marking / label	Data measurement
ST1-L/R MKII	Confirmed	Confirmed	Confirmed	Confirmed	Actual Finding

**3.0 WORKMANSHIP APPEARANCE / FUNCTION INSPECTION FINDINGS:**

(As according to Client's instruction "Critical and Major defect" are not allowed! And "Minor defects" are just for repair and improvement mainly!)

Model No	Defect description	Critical	Major	Minor
ST1-R MKII	Scratch mark on rear cabinet (S/N: S13605)	0	0	1

**4.0 PACKING**

Model No	Export packing	Individual packing
ST1-L/R MKII	2 ply corrugated carton and sealed by gummed tapes	Each unit was protected with poly bag and poly foam, then packed into carton together with accessories bag (3pcs spikes, 3pcs rubber caps, 2pcs plastic foot and 4pcs black screw, user's guide and warranty card.)

**5.0 MARKING / LABELING**

Model No	On Export carton
ST1-L / R MKII	<p><u>1). Shipping mark</u></p> <p style="text-align: center;"><b>Sapphire™</b> <b>ST1 MKII</b> High performance three-way Tower Speaker</p> <p><u>2). Side mark</u></p> <p><b>HANDLE WITH CARE</b> Designed and Engineered by Cary Christie And Tom DeVesto Exclusive 1" Sapphire Polycell Dome Tweeter 5.25" Aluminum Cone Midranges 8" side-firing woofer Magnetically Shielded Bi-Wirable Bass Reflex Design</p>

Page 2 of 3  
CII-D-CPS-

The Company under its General Conditions issues this report for inspection and testing services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Supulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fixed or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

19-AUG-2005 14:15 FROM SUNFIELD.COM.CN

TO 0088672240520

P.05/17

**SGS**Black Glass Top  
Grilles IncludedQuantity:  
One right Speaker  
Premium Black Ash VinylOne left Speaker  
Premium Black Ash VinylShipping:  
Wt: 52.7 lb  
Vol: 5.1 cu ft**Sapphire™**

RED HOT Blue!

One Broadway, Suite 600  
Cambridge, Massachusetts 02142 USA[www.SapphireAudio.com](http://www.SapphireAudio.com)

Sapphire and the Sapphire logo are trademarks of Sapphire audio.

MADE IN CHINA

3) Label:

3.1 UPC label stuck on export carton: 831623011117

3.2 Rating label stuck on rear cabinet.

3.3 Serial number label stuck on unit and export carton.

**6.0 DATA MEASUREMENT**

Model No	Data measurement
ST1-L/R MKII	1). AC Impedance curve found acceptable except defects shown in AQL. 2). Speaker polarity check found acceptable except defects shown in AQL. 3). Buzz & Rattle check found acceptable except defects shown in AQL. 4). 3pcs samples for actual installation check found acceptable. 5). 1 pc rubber foot for "left mark test" found acceptable.

**7.0 PROBLEM REMARKS / INFORMATIVE REMARKS**

Model No	Problem remark / Informative remark
ST1-L/R MKII	NIL

Page 3 of 3  
CN-D-OPS-

The Company under its General Conditions issues this report for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than three months.



2/F Oastar Building, Zhongkang Road, Shangmeilin, Shenzhen, China

Tele. (86 755) 83114358

Fax: (86 755) 83114354/ 83103194

## Inspection Report

Report Ref. No.: SZXWT000

To :	Tivoli Audio, LLC	Fax / E-mail:	tivolicon@aol.com
Att :	Tom Devesto		
Cc :	Sunfield Shenzhen	Fax / E-mail :	
Att :	Peter Peng		
From :	Hanson Cai	Fax / E-mail:	Hanson_cai@sgs.com
SGS File No.:	CN1US-	Date:05/05/04	SGS Registration No.: CN1US-

Buyer: Tivoli Audio, LLC

Agent: N/A

Supplier: Sunfield, TW

Manufacturer: Sunfield, ShenZhen

Product description: Speakers

L/C Number: (x) Not Available

P.O. Number: SF0501254/SF0501255

Service performed: FRI Inspection Date: 04-May-2004

Inspection Location: ShaJing, ShenZhen

REFERENCE SAMPLE PROVIDED:

By Principal (For data measurement only)

### 1.0 SUMMARY OF INSPECTION RESULT:

Model No	Quantity for inspection	AQL applied	Sample size	Overall result
N/A	N/A	According to Client instruction are using ANSI/ASQC Z1.4-1993, Single sampling plans for normal inspection AQL = Level I - according to letter code sample size only. Critical = Not allow Major = 0.65 Minor = 1.5	N/A	N/A
ST2 MKII	420		32	Confirmed

Note: Inspection results are defined as "Conformed" "Not conformed" "Not applicable" and "Subject to Client's Evaluation"

#### FOLLOW UP ACTIONS: (as applicable)

☐ Inspection certificate will be issued

☐ Supplier advised shipment scheduled for 5/4

Page 1 of 3  
ON-D-015

The Company under its General Conditions issues this report for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

Three months



**SGS****Grilles Included**

**Quantity:**  
One right Speaker  
Premium Black Ash Vinyl

One left Speaker  
Premium Black Ash Vinyl

**Shipping:**  
Wt: 60.5 lb  
Vol: 6.1 cu ft

**Sapphire™****RED HOT Blue!**

One Broadway, Suite 800  
Cambridge, Massachusetts 02142 USA

[www.SapphireAudio.com](http://www.SapphireAudio.com)

Sapphire and the Sapphire logo are trademarks of Sapphire audio.

**MADE IN CHINA****3) Label:**

3.1 UPC label stuck on export carton: 831623D12114

3.2 Rating label stuck on rear cabinet.

3.3 Serial number label stuck on unit and export carton.

**6.0 DATA MEASUREMENT**

Model No	Data measurement
ST2 MKII	1). AC Impedance curve found acceptable except defects shown in AQL. 2). Speaker polarity check found acceptable except defects shown in AQL. 3). Buzz & Rattle check found acceptable except defects shown in AQL. 4). 3pcs samples for actual installation check found acceptable.

**7.0 PROBLEM REMARKS / INFORMATIVE REMARKS**

Model No	Problem remark / Informative remark
ST2 MKII	NIL



19-AUG-2005 14:16 FROM SUNFIELD.COM.CN

TO 0088672240520

P.08/17

**SGS***Draft Report*

2/F Oastar Building, Zhongkang Road, Shangmeilin, Shenzhen, China

Tele. (86 755) 83114358

Fax: (86 755) 83114354/ 83103194

**Inspection Report**

Report Ref. No.: SZXWT00122214

To :	Tivoli Audio, LLC	Fax / E-mail:	tivolicon@aol.com
Att :	Tom Devesto		
Cc :	Sunfield Shenzhen	Fax / E-mail :	
Att :	Peter Peng		
From :	Hanson Cai	Fax / E-mail:	Hanson_cai@sgs.com
SGS File No.:	CN1US-079377	Date:10/May/2005	SGS Registration CN1US-079377

Buyer: Tivoli Audio, LLC

Agent: N/A

Supplier: Sunfield, TW

Manufacturer: Sunfield, ShenZhen

Product description: Speakers

L/C Number: (x) Not Available

P.O. Number: SF0501252

SF0501253

Service performed: FRI

Inspection Date: 10-MAY-2005

Inspection Location: Shajing, ShenZhen

REFERENCE SAMPLE PROVIDED:

By Principal (For data measurement only)

**1.0 SUMMARY OF INSPECTION RESULT:**

Model No	Quantity for inspection	AQL applied	Sample size	Overall result
ST1- L/R MKII	740	According to Client instruction are using ANSI/ASQC Z1.4-1993, Single sampling plans for normal inspection AQL = Level I - according to letter code sample size only. Critical = Not allow Major = 0.65 Minor = 1.5	32	Not confirmed

Note: Inspection results are defined as "Conformed" "Not conformed" "Not applicable" and "Subject to Client's Evaluation"

**FOLLOW UP ACTIONS:** (as applicable)

: Inspection certificate will be issued

: Supplier advised shipment scheduled for

Page 1 of 4  
CHU-CPE

The Company under its General Conditions issues this report for inspection and Testing Services. (copy available upon request) The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Exceptions to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

19-AUG-2005 14:17 FROM SUNFIELD.COM.CN

TO 0088672240520

P.09/17

**SGS**

1. Manufacturer / supplier commented on inspection result as follow: \_\_\_\_\_

2. Please instruct regarding issuance of inspection certificate.

3. We sent you defective samples by \_\_\_\_\_ AWB. No.: \_\_\_\_\_ on \_\_\_\_\_. Please advise your evaluation.

4. We recommend the following corrective action: \_\_\_\_\_

5. Additional SGS service \_\_\_\_\_ results due by \_\_\_\_\_

**2.0 SUMMARY OF INSPECTION CONTENTS**

Model No	Style / Material / Color	Workmanship / Visual / Function	Packing	Marking / label	Data measurement Actual Finding
ST1-L/R MKII	Confirmed	Confirmed	Confirmed	Confirmed	

**3.0 WORKMANSHIP APPEARANCE / FUNCTION INSPECTION FINDINGS:**

(As according to Client's instruction "Critical and Major defect" are not allowed! And "Minor defects" are just for repair and improvement mainly!)

Model No	Defect description	Critical	Major	Minor
ST1-R MKII	Scratch mark on rear cabinet. (S/N: S13605)	0	0	1

**4.0 PACKING**

Model No	Export packing	Individual packing
ST1-L/R MKII	2 ply corrugated carton and sealed by gummed tapes	Each unit was protected with poly bag and poly foam, then packed into carton together with accessories bag (3pcs spikes, 3pcs rubber caps, 2pcs plastic foot and 4pcs black screw, user's guide and warranty card.)

**5.0 MARKING / LABELING**

Model No	On Export carton
ST1-L / R MKII	<p>1). Shipping mark</p> <p style="text-align: center;"><b>Sapphire™</b> <b>ST1 MKII</b> High performance three-way Tower Speaker</p> <p>2). Side mark</p> <p><b>HANDLE WITH CARE</b> Designed and Engineered by Cary Christie And Tom DeVesto Exclusive 1" Sapphire Polycell Dome Tweeter 5.25" Aluminum Cone Midranges 8" side-firing woofer Magnetically Shielded Bi-Wirable Bass Reflex Design</p>

Page 2 of 3  
CH-0000

The Company under its General Conditions issues this report for inspection and testing services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Disputations in the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees of commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

Best three months

19-AUG-2005 14:17 FROM SUNFIELD.COM.CN

TO 0088672240520

P.10/17

**SGS**

Draft report

2/F Oastar Building, Zhongkang Road, Shangmeilin, Shenzhen, China

Tele.: (86 755) 83114358

Fax: (86 755) 83114354/ 83103194

**Inspection Report**

Report Ref. No.: SZXWT00120275

To :	Sapphire	Fax / E-mail :	tivolicon@aol.com
Att :	Tom Devesto		
Cc :	Sunfield Shenzhen	Fax / E-mail :	
Att :	Peter Peng		
From :	Hanson Cai	Fax / E-mail :	Hanson_cai@sgs.com
SGS File No.:	CN1US-077489	Date: 19/ April/2005	SGS Registration No.: CN1US-077489

Buyer : Sapphire  
 Agent : N/A  
 Supplier : Sunfield, TW  
 Manufacturer : Sunfield, Shen Zhen  
 Product description: Speaker box

L/C Number : (x) Not Available  
 P.O. Number: SF05012567/8 (x) Not Available

Service performed : FRI Inspection Date : 19-April- 2005  
 Inspection Location : Sha Jing, Shen Zhen



REFERENCE SAMPLE PROVIDED :

By Principal (For data measurement only)

**1.0 SUMMARY OF INSPECTION RESULT :**

Model No	Quantity for Inspection	AQL applied	Sample size	Overall result
SBS	200pcs	According to Client instruction are using ANSI/ASQC Z1.4-1993, Single sampling plans for normal inspection ;  AQL = Level I letter code Critical = Not allow Major = 0.65 Minor = 1.5	20	Subject to Client's evaluation
ST3-L MKII	35 pcs		15	Subject to Client's evaluation
ST3-R MKII	5 pcs		5	Subject to Client's evaluation

Note : Inspection result are defined as "Conformed" "Not conformed" "Not applicable" and "Subject to Client's evaluation"

**FOLLOW UP ACTIONS : (as applicable)**

- ☐ Inspection certificate will be issued  
☐ Supplier advised shipment scheduled for \_\_\_\_\_  
☐ Manufacturer / supplier commented on inspection result as follow: \_\_\_\_\_  
☐ Please instruct regarding issuance of inspection certificate.

Page 1 of 4  
 CN-D-OPS-

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for

附单号 4/19

19-AUG-2005 14:17 FROM SUNFIELD.COM.CN

TO 0088672240520

P.11/17



☐ We sent you defective samples by \_\_\_\_\_ AWB. No.: \_\_\_\_\_ on \_\_\_\_\_. Please advise your evaluation.

☐ We recommend the following corrective action: \_\_\_\_\_

☐ Additional SGS service \_\_\_\_\_ results due by \_\_\_\_\_

## 2.0 SUMMARY OF INSPECTION CONTENTS

Model No	Style / Material / Color	Workmanship / Visual / Function	Packing	Marking / label	Data measurement
SBS	Conformed	Pass AQL	Conformed	Conformed	Actual Finding
ST3-L MKII	Conformed	Pass AQL	Conformed	Conformed	Actual Finding
ST3-R MKII	Conformed	Pass AQL	Conformed	Conformed	Actual Finding

## 3.0 WORKMANSHIP APPEARANCE / FUNCTION INSPECTION FINDINGS:

( As according to Client's instruction "Critical and Major defect" are not allow !  
And "Minor defect" are just for repair and improvement mainly ! )

Model No	Defect description	Critical	Major	Minor
SBS	White edge on front.	0	0	1
ST3-L MKII	No found defect.	0	0	0
ST3-L MKII	No found defect.	0	0	0

## 4.0 PACKING

Model No	Export packing	Individual packing
SBS	2 ply corrugated carton and sealed by gummed tapes	Each unit protected with poly bag and foam, and then packed into carton together with accessories bag (8 pcs rubber foot), User's guide and Warranty card.
ST3-L / R MKII	2 ply corrugated carton and sealed by gummed tapes	Each unit was protected with poly bag and poly foam, and then packed into carton together with accessories bag (3pcs spikes, 3pcs rubber caps, 2pcs plastic foot and 4pcs black screw) user's guide and warranty card.

## 5.0 MARKING / LABELING

Model No	On Export carton
SBS	<p>1). Shipping mark</p> <p style="text-align: center;">Sapphire™ <b>SBS</b> Two-way High Performance Bookshelf Speakers</p> <p style="text-align: center;">Quantity: Two</p> <p>2). Side mark</p>

Page 2 of 4  
CN-D-OPS

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations in the contract are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no way be

19-AUG-2005 14:18 FROM SUNFIELD.COM.CN

TO 0088672240520

P.12/17

**SGS**

	<p>RED HOT Blue!</p> <p>One Broadway, Suite 600 Cambridge, Massachusetts 02142 USA <a href="http://www.SapphireAudio.com">www.SapphireAudio.com</a> Sapphire and the Sapphire logo are trademarks of Sapphire audio MADE IN CHINA</p> <p>3) Label: 3.1 UPC label stuck on export carton: 831623013111 3.2 Rating label stuck on rear cabinet. 3.3 Serial number label stuck on unit and export carton.</p>
--	--

**6.0 DATA MEASUREMENT**

Model No	Data measurement
SBS	<p>1). AC Impedance curve found acceptable except defects shown in AQL.</p> <p>2). Speaker polarity check found acceptable except defects shown in AQL.</p> <p>3). Buzz &amp; Rattle check found acceptable except defects shown in AQL.</p> <p>4). 3pcs samples for actual installation check found acceptable.</p> <p>5). 1 pc rubber foot for "left mark test" found acceptable.</p>
ST3-L/R MKII	<p>1). AC Impedance curve found acceptable except defects shown in AQL.</p> <p>2). Speaker polarity check found acceptable except defects shown in AQL.</p> <p>3). Buzz &amp; Rattle check found acceptable except defects shown in AQL.</p> <p>4). 1 pc rubber foot for "left mark test" found acceptable.</p>

**7.0 PROBLEM REMARKS / INFORMATIVE REMARKS**

Model No	Problem remark / Informative remark
ST3-L	Actual quantity of product is 35pcs, which did not conform to inspection booking stated as 40pcs.
ST3-R	Actual quantity of product is 5pcs, which did not conform to inspection booking stated as 40pcs.

Page 4 of 4  
CN-D-002-

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than ten times the amount of the fees or commission.



2/F Oastar Building, Zhongkang Road, Shangmeilin, Shenzhen, China  
 Tele. (86 755) 83114358  
 Fax: (86 755) 83114354/ 83103194

## Inspection Report

Report Ref. No.: SZXWT00121631

To :	Sapphire Audio, LLC	Fax / E-mail:	
Att :	Tom Devesto		
Cc :	Sunfield Shenzhen	Fax / E-mail :	
Att :	Peter Peng		
From :	Hanson Cai	Fax / E-mail:	Hanson_cai@sgs.com
SGS File No.:	CN1US-078943	Date:07/05/05	SGS Registration No.: CN1US-078943

Buyer: Sapphire Audio, LLC  
 Agent: N / A  
 Supplier: Sunfield, TW  
 Manufacturer: Sunfield, ShenZhen  
 Product description: Speakers

L/C Number: (x) Not Available  
 P.O. Number: SF0501254/SF0501255

Service performed: FRI Inspection Date: 04 -May - 2004  
 Inspection Location: ShaJing, ShenZhen

REFERENCE SAMPLE PROVIDED: By Principal (For data measurement only)

### 1.0 SUMMARY OF INSPECTION RESULT :

Model No	Quantity for inspection	AQL applied	Sample size	Overall result
N/A	N/A	According to Client instruction are using ANSI/ASQC Z1.4-1993, Single sampling plans for normal inspection	N/A	N/A
ST2 MKII	420	AQL = Level I - according to letter code sample size only. Critical = Not allow Major = 0.65 Minor = 1.5	32	Conformed

Note: Inspection results are defined as "Conformed" "Not conformed" "Not applicable" and "Subject to Client's Evaluation"

#### FOLLOW UP ACTIONS: (as applicable)

Inspection certificate will be issued

Supplier advised shipment scheduled for \_\_\_\_\_



# SGS

Manufacturer / supplier commented on inspection result as follow: \_\_\_\_\_

Please instruct regarding issuance of inspection certificate.

We sent you defective samples by \_\_\_\_\_ AWB. No.: \_\_\_\_\_ on \_\_\_\_\_ Please advise your evaluation.

We recommend the following corrective action \_\_\_\_\_

Additional SGS service \_\_\_\_\_ results due by \_\_\_\_\_

## 2.0 SUMMARY OF INSPECTION CONTENTS

Model No	Style / Material / Color	Workmanship / Visual / Function	Packing	Marking / label	Data measurement
ST2 MKII	Confirmed	Confirmed	Confirmed	Confirmed	Actual Finding

## 3.0 WORKMANSHIP APPEARANCE / FUNCTION INSPECTION FINDINGS:

(As according to Client's instruction "Critical and Major defect" are not allowed! And "Minor defects" are just for repair and improvement mainly! )

Model No	Defect description	Critical	Major	Minor
ST2 MKII	Glue mark at zone B. (13318)	0	0	1

## 4.0 PACKING

Model No	Export packing	Individual packing
ST2 MKII	2 ply corrugated carton and sealed by gummed tapes	Each unit was protected with poly bag and poly foam, then packed into carton together with accessories bag (3pcs spikes, 3pcs rubber caps, 2pcs plastic foot and 4pcs black screw, user's guide and warranty card.)

## 5.0 MARKING / LABELING

Model No	On Export carton
ST2 MKII	<p>1). Shipping mark</p> <p style="text-align: center;"><b>Sapphire™</b> <b>ST2 MKII</b> High performance three-way Tower Speaker</p> <p>2). Side mark</p> <p><b>HANDLE WITH CARE</b> Designed and Engineered by Cary Christie And Tom DeVesto Exclusive 1" Sapphire Polycell Dome Tweeter 2X5.25" Aluminum Cone Midranges 10" side-firing woofer Magnetically Shielded BI-Wirable Bass Reflex Design Black Glass Top</p>

Page 2 of 3  
CN-D-OPS-

The Company under its General Conditions issues this report for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.



# SGS

## Grilles Included

Quantity:  
One right Speaker  
Premium Black Ash Vinyl

One left Speaker  
Premium Black Ash Vinyl

Shipping:  
Wt: 60.5 lb  
Vol: 6.1 cu ft

**Sapphire™**  
RED HOT Blue!  
One Broadway, Suite 600  
Cambridge, Massachusetts 02142 USA  
[www.SapphireAudio.com](http://www.SapphireAudio.com)  
Sapphire and the Sapphire logo are trademarks of Sapphire audio.  
MADE IN CHINA

3) Label:  
3.1 UPC label stuck on export carton: 831623012114  
3.2 Rating label stuck on rear cabinet.  
3.3 Serial number label stuck on unit and export carton.

## 6.0 DATA MEASUREMENT

Model No	Data measurement
ST2 MKII	1). AC Impedance curve found acceptable except defects shown in AQL. 2). Speaker polarity check found acceptable except defects shown in AQL. 3). Buzz & Rattle check found acceptable except defects shown in AQL. 4). 3pcs samples for actual installation check found acceptable.

## 7.0 PROBLEM REMARKS / INFORMATIVE REMARKS

Model No	Problem remark / Informative remark
ST2 MKII	NIL



2/F Oasfar Building, Zhongkang Road, Shangmellin, Shenzhen, China

Tele.: (86 755) 83114358  
Fax: (86 755) 83114354/ 83103194

## Inspection Report

Report Ref. No.: SZXWT00120275

To :	Sapphire Audio LCC	Fax / E-mail:	
Att :	Tom Devesto		
Cc :	Sunfield Shenzhen	Fax / E-mail:	
Att :	Peter Peng		
From :	Hanson Cai	Fax / E-mail:	Hanson_cai@sgs.com
SGS File No.:	CN1US-077489	Date: 20/April/2005	SGS Registration No.: CN1US-077489

Buyer: Sapphire Audio LCC  
Agent: N/A  
Supplier: Sunfield, TW  
Manufacturer: Sunfield, Shen Zhen  
Product description: Speaker box

L/C Number: Not Available  
P.O. Number: SF0501256/7/8

Service performed: FRI Inspection Date: 19-April-2005  
Inspection Location: Sha Jing, Shen Zhen

REFERENCE SAMPLE PROVIDED: By Principal (For data measurement only)

### 1.0 SUMMARY OF INSPECTION RESULT:

Model No	Quantity for Inspection	AQL applied	Sample size	Overall result
SBS	200pcs	According to Client instruction are using ANSI/ASQC Z1.4-1993, Single sampling plans for normal inspection ;  AQL = Level I letter code Critical = Not allow Major = 0.65 Minor = 1.5	20	Subject to Client's evaluation
ST3-L MKII	35 pcs		15	Subject to Client's evaluation
ST3-R MKII	5 pcs		5	Subject to Client's evaluation

Note: Inspection result are defined as "Conformed" "Not conformed" "Not applicable" and "Subject to Client's evaluation"

### FOLLOW UP ACTIONS: (as applicable)

Inspection certificate will be issued

Supplier advised shipment scheduled for \_\_\_\_\_

Manufacturer / supplier commented on inspection result as follow: \_\_\_\_\_

Please instruct regarding issuance of inspection certificate.

Page 1 of 4  
CN-D-OPS-

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

# SGS

We sent you defective samples by \_\_\_\_\_ AWB. No.: \_\_\_\_\_ on \_\_\_\_\_ Please advise your evaluation.

We recommend the following corrective action \_\_\_\_\_

Additional SGS service \_\_\_\_\_ results due by \_\_\_\_\_

## 2.0 SUMMARY OF INSPECTION CONTENTS

Model No	Style / Material / Color	Workmanship / Visual / Function	Packing	Marking / label	Data measurement
SBS	Conformed	Pass AQL	Conformed	Conformed	Actual Finding
ST3-L MKII	Conformed	Pass AQL	Conformed	Conformed	Actual Finding
ST3-R MKII	Conformed	Pass AQL	Conformed	Conformed	Actual Finding

## 3.0 WORKMANSHIP APPEARANCE / FUNCTION INSPECTION FINDINGS:

(As according to Client's instruction "Critical and Major defect" are not allowed!  
And "Minor defect" are just for repair and improvement mainly!)

Model No	Defect description	Critical	Major	Minor
SBS	White edge on front. (13892)	0	0	1
ST3-L MKII	No found defect.	0	0	0
ST3-L MKII	No found defect.	0	0	0

## 4.0 PACKING

Model No	Export packing	Individual packing
SBS	2 ply corrugated carton and sealed by gummed tapes	Each unit protected with poly bag and foam, and then packed into carton together with accessories bag (8 pcs rubber foot), User's guide and Warranty card.
ST3-L/ R MKII	2 ply corrugated carton and sealed by gummed tapes	Each unit was protected with poly bag and poly foam, and then packed into carton together with accessories bag (3pcs spikes, 3pcs rubber caps, 2pcs plastic foot and 4pcs black screw) user's guide and warranty card.

## 5.0 MARKING / LABELING

Model No	On Export carton
SBS	<p>1). Shipping mark</p> <p style="text-align: center;">Sapphire™ <b>SBS</b> Two-way High Performance Bookshelf Speakers</p> <p style="text-align: center;">Quantity: Two</p> <p>2). Side mark</p> <p><b>HANDLE WITH CARE</b></p>

Page 2 of 4  
CN-D-OPS-

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

# SGS

	<p>Designed and Engineered by Cary Christie And Tom DeVesto Exclusive 1" Polycell Dome Sapphire Tweeter Magnetically Shielded 5.25" coated paper Cone midrange/woofer Bass Reflex Design</p> <p>Quantity: Two Speakers Premium Black Ash Vinyl</p> <p>Shipping: Wt: 21.5 lb Vol: 1.8 cu ft</p> <p><b>Sapphire™</b> RED HOT Blue! One Broadway, Suite 600 Cambridge, Massachusetts 02142 USA <a href="http://www.SapphireAudio.com">www.SapphireAudio.com</a> Sapphire and the Sapphire logo are trademarks of Sapphire audio. MADE IN CHINA</p>
ST3-L/R MKII	<p>1). <u>Shipping mark</u></p> <p style="text-align: center;"><b>Sapphire™</b> <b>ST3 MKII</b> High performance three-way Tower Speaker</p> <p>2). <u>Side mark</u></p> <p><b>HANDLE WITH CARE</b> Designed and Engineered by Cary Christie And Tom DeVesto Exclusive 1" Sapphire Polycell Dome Tweeter 2x5.25" Aluminum Cone Midranges 2x8" side-firing woofer Magnetically Shielded BI-Wirable Bass Reflex Design Black Glass Top Grilles Included</p> <p>Quantity: One right/left Speaker Premium Black Ash Vinyl</p> <p>One left Speaker Premium Black Ash Vinyl</p> <p>Shipping: Wt: 76.6 lb Vol: 7.1 cu ft</p> <p><b>Sapphire™</b> RED HOT Blue! One Broadway, Suite 600</p>

Page 3 of 4  
CN-D-OPS-

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

# SGS

Cambridge, Massachusetts 02142 USA  
[www.SapphireAudio.com](http://www.SapphireAudio.com)  
 Sapphire and the Sapphire logo are trademarks of Sapphire audio.  
 MADE IN CHINA

3) Label:

3.1 UPC label stuck on export carton: 831623013111

3.2 Rating label stuck on rear cabinet.

3.3 Serial number label stuck on unit and export carton.

## 6.0 DATA MEASUREMENT

Model No	Data measurement
SBS	1). AC Impedance curve found acceptable except defects shown in AQL. 2). Speaker polarity check found acceptable except defects shown in AQL. 3). Buzz & Rattle check found acceptable except defects shown in AQL. 4). 3pcs samples for actual installation check found acceptable. 5). 1 pc rubber foot for "left mark test" found acceptable.
ST3-L/R MKII	1). AC Impedance curve found acceptable except defects shown in AQL. 2). Speaker polarity check found acceptable except defects shown in AQL. 3). Buzz & Rattle check found acceptable except defects shown in AQL. 4). 1 pc rubber foot for "left mark test" found acceptable.

## 7.0 PROBLEM REMARKS / INFORMATIVE REMARKS

Model No	Problem remark / Informative remark
ST3-L	Actual quantity of product is 35pcs, which did not conform to inspection booking stated as 40pcs.
ST3-R	Actual quantity of product is 5pcs, which did not conform to inspection booking stated as 40pcs.

19-AUG-2005 14:18 FROM SUNFIELD.COM.CN

TO 0088672240520  
1/1/05 + reply P.13/17**SGS**

2/F Dastar Building, Zhongkang Road, Shangmellin, Shenzhen, China

Tel.: (86 755) 83114358  
Fax: (86 755) 83114354/ 83103194**Inspection Report**

Report Ref. No.: SZXWT0011951

To :	Sapphire Audio, LLC	Fax / E-mail :	
Attn :	Tom Devesto		
Cc :	Sunfield Shenzhen	Fax / E-mail :	
Attn :	Peter Peng		
From :	Hanson Cai	Fax / E-mail :	Hanson_cai@sgs.com
SGS File No.:	CN1US-077081	Date:	12/04/2005
		SGS Registration No.:	CN1US-077081

Buyer : Sapphire  
 Agent : N/A  
 Supplier : Sunfield, TW  
 Manufacturer : Sunfield, Shen Zhen  
 Product description : SPEAKER BOX

L/C Number : \_\_\_\_\_ (x) Not Available  
 P.O. Number : 5F0501254 / 5F0501255 ( ) Not Available

Service performed : FRI Inspection Date : 12/04/2005  
 Inspection Location : Sha Jing, Shen Zhen

REFERENCE SAMPLE PROVIDED : By Principal ( For data measurement only )

**1.0 SUMMARY OF INSPECTION RESULT :**

Model No	Quantity for Inspection	AQL applied	Sample size	Overall result
ST2 MKII	400	According to Client instruction are using ANSI/ASQC Z1.4-1993, Single sampling plans for normal inspection ; AQL = Level I letter code Critical = Not allow Major = 0.65 Minor = 1.5	20 pcs for major/32pcs for minor	Conformed

Remark : Only provided 400 PLS for our inspection. (ST2-L 200 PLS / ST2-R 200 PLS)  
 Note : Inspection result are defined as "Conformed" "Not conformed" "Not applicable" and "Subject to Client's evaluation"

**FOLLOW UP ACTIONS : ( as applicable )**

- ☐ Inspection certificate will be issued  
☐ Supplier advised shipment scheduled for \_\_\_\_\_  
☐ Manufacturer / supplier commented on inspection result as follow : \_\_\_\_\_  
☐ Please instruct regarding issuance of inspection certificate.  
☐ We sent you defective samples by \_\_\_\_\_ AWB. No.: \_\_\_\_\_ on \_\_\_\_\_ Please advise your evaluation.

Page 1 of 3

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

19-AUG-2005 14:19 FROM SUNFIELD.COM,CN

TO 0088672240520

P.14/17

**SGS**Shipping:  
Wt: 60.5 lb  
Vol: 6.1 cu ft**Sapphire™**

RED HOT Blue!

One Broadway, Suite 600

Cambridge, Massachusetts 02142 USA

[www.SapphireAudio.com](http://www.SapphireAudio.com)

Sapphire and the Sapphire logo are trademarks of Sapphire audio.

MADE IN CHINA

**6.0 DATA MEASUREMENT**

Model No	Data measurement
ST2 MKII	1). AC Impedance curve found acceptable except defects shown in AQL. 2). Speaker polarity check found acceptable except defects shown in AQL.. 3). Buzz & Rattle check found acceptable except defects shown in AQL.. 4). 1 pc rubber foot for "left mark test" found acceptable. 5). 3 pcs samples for actual installation check found acceptable.

**7.0 PROBLEM REMARKS / INFORMATIVE REMARKS**

Model No	Problem remark / Informative remark
ST2 MKII	1. UPC label stuck on export carton: 831623012114 2. Rating label stuck on rear cabinet. 3. Serial number label stuck on unit and export carton.



19-AUG-2005 14:30 FROM SUNFIELD.COM.CN

TO 0088672240520

P.12/23

**SGS**

R Oester Building, Zhongkang Road, Shangmeilin, Shenzhen, China

Tele: (86 755) 83114358

Fax: (86 755) 83114354/ 83103194

**Inspection Report**

Report Ref. No.: SZXWT00119037

To :	Sapphire Audio, LLC	Fax / E-mail :	
Att :	Tom Devesto		
Cc :	Sunfield Shenzhen	Fax / E-mail :	
Att :	Peter Peng		
From :	Hanson Cai	Fax / E-mail :	Hanson_cai@sgs.com
SGS File No.:	CN1US-076691	Date:07/04/2005	SGS Registration No.: CN1US-076691

Buyer: Tivoli Audio, LLC  
 Agent: N/A  
 Supplier: Sunfield, TW  
 Manufacturer: Sunfield, Shen Zhen  
 Product description: Speakers and Grill kits

L/C Number: (x) Not Available  
 P.O. Number: (x) Not Available

Service performed: FRI Inspection Date: 07/04/2005  
 Inspection Location: Sha Jing, Shen Zhen

REFERENCE SAMPLE PROVIDED:

By Principal (For data measurement only)

**1.0 SUMMARY OF INSPECTION RESULT:**

Model No	Quantity for inspection	AQL applied	Sample size	Overall result
ST1 MKII	490	According to Client instruction are using ANSI/ASQC Z1.4-1993, Single sampling plans for normal inspection; AQL = Level I letter code Critical = Not allow Major = 0.65 Minor = 1.5	20 pcs for major/32pcs for minor	Conformed

Note: Inspection result are defined as "Conformed" "Not conformed" "Not applicable" and "Subject to Client's evaluation"

**FOLLOW UP ACTIONS: (as applicable)**☐ Inspection certificate will be issued☐ Supplier advised shipment scheduled for \_\_\_\_\_☐ Manufacturer / supplier commented on inspection result as follow: \_\_\_\_\_☐ Please instruct regarding issuance of inspection certificate.

☐ We sent you defective samples by \_\_\_\_\_ AWB. No.: \_\_\_\_\_ on \_\_\_\_\_ Please advise your evaluation.

Page 1 of 3

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees of commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

19-AUG-2005 14:30 FROM SUNFIELD.COM.CN

TO 0088672240520

P.13/23

**SGS**

☐ We recommend the following corrective action \_\_\_\_\_  
☐ Additional SGS service \_\_\_\_\_ results due by \_\_\_\_\_

**2.0 SUMMARY OF INSPECTION CONTENTS**

Model No	Style / Material / Color	Workmanship / Visual / Function	Packing	Marking / label	Data measurement
ST1 MKII	Conformed	Pass AQL	Conformed	Conformed	Actual Finding

**3.0 WORKMANSHIP APPEARANCE / FUNCTION INSPECTION FINDINGS:**


(As according to Client's instruction "Critical and Major defect" are not allowed!  
 And "Minor defect" are just for repair and improvement mainly!)

Model No	Defect description	Critical	Major	Minor
ST1	Dirty mark on speaker cabinet. (S/N: 13398)	0	0	1

**4.0 PACKING**

Model No	Export packing	Individual packing
ST1 MKII	2 ply corrugated carton and sealed by gummed tapes	Each speaker protected with polybag and foam, then packed into carton together with accessories bag (3pcs spikes, 2pcs plastic foot, 3pcs rubber caps and 4pcs black screw), User's guide and Warranty card.

**5.0 MARKING / LABELING**

Model No	On Export carton
 MKII	<p>1). Shipping mark</p> <p style="text-align: center;">Sapphire™ ST1 MKII High Performance Three-way Tower Speaker</p> <p>2). Side mark</p> <p><b>HANDLE WITH CARE</b>          Designed and Engineered by Cary Christie          And Toni DeVesto          Exclusive 1Sapphire Polcoli Dome Tweeter          5.25" Aluminum Cone Midrange          8" Side-firing Woofer          Magnetically Shielded          Bi-Wirable          Bass Reflex Design          Black Glass Top          Grilles Included</p> <p>Quantity:          One Right Speaker          Premium Black Ash Vinyl          One left Speaker          Premium Black Ash Vinyl</p>

Page 2 of 3

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Signatures and stamps are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than three months.

19-AUG-2005 14:31 FROM SUNFIELD.COM.CN

TO 0088672240520

P.14/23

**SGS****Shipping:**

Wt: 52.7 lb

Vol: 5.1 cu ft

**Sapphire™**

RED HOT Blue!

One Broadway, Suite 600

Cambridge, Massachusetts 02142 USA

[www.SapphireAudio.com](http://www.SapphireAudio.com)

Sapphire and the Sapphire logo are trademarks of Sapphire audio.

MADE IN CHINA

**6.0 DATA MEASUREMENT**

Model No	Data measurement
ST1 MKII	1). AC Impedance curve found acceptable except defects shown in AQL. 2). Speaker polarity check found acceptable except defects shown in AQL. 3). Buzz & Rattle check found acceptable except defects shown in AQL. 4). 1 pc rubber foot for "left mark test" found acceptable. 5). 3 pcs samples for actual installation check found acceptable.

**7.0 PROBLEM REMARKS / INFORMATIVE REMARKS**

Model No	Problem remark / Informative remark
ST1 MKII	1. UPC label stuck on export carton: 831623011117 2. Rating label stuck on rear cabinet. 3. Serial number label stuck on unit and export carton.



2/F Oastar Building, Zhongkang Road, Shangmeilin, Shenzhen ,China

Tele.: (86 755) 83114358

Fax: (86 755) 83114354/ 83103194

## Inspection Report

Report Ref. No.: SZXWT00119521

To :	Sapphire Audio, LLC	Fax / E-mail:	
Att :	Tom Devesto		
Cc :	Sunfield Shenzhen	Fax / E-mail :	
Att :	Peter Peng		
From :	Hanson Cai	Fax / E-mail:	Hanson_cai@sgs.com
SGS File No.:	CN1US-077081	Date: 13/04/2005	SGS Registration No.: CN1US-077081

Buyer: Sapphire Audio, LLC

Agent: N/A

Supplier: Sunfield, TW

Manufacturer: Sunfield, Shen Zhen

Product description: Speakers

L/C Number: Not Available

P.O. Number: SF0501254/SF0501255

Service performed: FRI

Inspection Date: 12/04/2005

Inspection Location: Sha Jing, Shen Zhen

### REFERENCE SAMPLE APROVIDED:

By Principal (For data measurement only)

### 1.0 SUMMARY OF INSPECTION RESULT:

Model No	Quantity for inspection	AQL applied	Sample size	Overall result
ST1MK II	0	According to Client instruction are using ANSI/ASQC Z1.4-1993, Single sampling plans for normal inspection; AQL = Level I letter code Critical = Not allow Major = 0.65 Minor = 1.5	0	Not conformed
ST2 MKII	400		20 pcs for major/32pcs for minor	Subject to client's decision

**Note:** Inspection result are defined as "Conformed" "Not conformed" "Not applicable" and "Subject to Client's evaluation".

### FOLLOW UP ACTIONS: (as applicable)

Inspection certificate will be issued

Supplier advised shipment scheduled for \_\_\_\_\_

Manufacturer / supplier commented on inspection result as follow: \_\_\_\_\_

Please instruct regarding issuance of inspection certificate.

We sent you defective samples by \_\_\_\_\_ AWB. No.: \_\_\_\_\_ on \_\_\_\_\_ Please advise your evaluation?

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.



We recommend the following corrective action \_\_\_\_\_  
 Additional SGS service \_\_\_\_\_ results due by \_\_\_\_\_

## 2.0 SUMMARY OF INSPECTION CONTENTS

Model No	Style / Material / Color	Workmanship / Visual / Function	Packing	Marking / label	Data measurement
ST2 MKII	Conformed	Pass AQL	Conformed	Conformed	Actual Finding

## 3.0 WORKMANSHIP APPEARANCE / FUNCTION INSPECTION FINDINGS:

(As according to Client's instruction "Critical and Major defect" are not allowed!  
 And "Minor defect" are just for repair and improvement mainly! )

Model No	Defect description	Critical	Major	Minor
ST2 MKII	White dot on rear cabinet. (13018)	0	0	1

## 4.0 PACKING

Model No	Export packing	Individual packing
ST2 MKII	2 ply corrugated carton and sealed by gummed tapes	Each speaker protected with poly bag and foam, then packed into carton together with accessories bag (3pcs spikes, 2pcs plastic foot, 3pcs rubber caps and 4pcs black screw), User's guide and Warranty card.

## 5.0 MARKING / LABELING

Model No	On Export carton
ST2 MKII	<p><u>1). Shipping mark</u></p> <p style="text-align: center;">Sapphire™  <b>ST2 MKII</b>          High Performance Three-way Tower Speaker</p> <p><u>2). Side mark</u></p> <p><b>HANDLE WITH CARE</b>          Designed and Engineered by Cary Christie          And Tom DeVesto          Exclusive 1Sapphire Polcell Dome Tweeter          2X5.25" Aluminum Cone Midrange          10" Side-firing Woofer          Magnetically Shielded          Bi-Wirable          Bass Reflex Design          Black Glass Top          Grilles Included</p> <p>Quantity:          One Right Speaker          Premium Black Ash Vinyl          One left Speaker          Premium Black Ash Vinyl</p>

Page 2 of 3

# SGS

Shipping:  
Wt: 60.5 lb  
Vol: 6.1 cu ft

**Sapphire™**

RED HOT Blue!

One Broadway, Suite 600

Cambridge, Massachusetts 02142 USA

[www.SapphireAudio.com](http://www.SapphireAudio.com)

Sapphire and the Sapphire logo are trademarks of Sapphire audio.

MADE IN CHINA

## 6.0 DATA MEASUREMENT

Model No	Data measurement
ST2 MKII	1). AC Impedance curve found acceptable except defects shown in AQL. 2). Speaker polarity check found acceptable except defects shown in AQL. 3). Buzz & Rattle check found acceptable except defects shown in AQL. 4). 1 pc rubber foot for "left mark test" found acceptable. 5). 3 pcs samples for actual installation check found acceptable.

## 7.0 PROBLEM REMARKS / INFORMATIVE REMARKS

Model No	Problem remark / Informative remark
ST2 MKII	1. UPC label stuck on export carton: 831623012114 2. Rating label stuck on rear cabinet. 3. Serial number label stuck on unit and export carton. 4. Manufactory only provided 400 pcs of goods for inspection during inspection that did not conform to the P/O Qty: 500 pcs.



19-AUG-2005 14:31 FROM SUNFIELD.COM.CN

TO 0088672240520

P.15/23

**SGS**

2/F Oastar Building, Zhongkang Road, Shangmeilin, Shenzhen, China

Tele: (86 755) 83114368

Fax: (86 755) 83114354/83103194

**Inspection Report**

Report Ref. No.: SZXWT00118828

To :	Tivoli Audio, LLC	Fax / E-mail :	tivolicon@aol.com
Alt :	Tom Devesto		
Cc :	Sunfield Shenzhen	Fax / E-mail :	
All :	Peter Peng		
From :	Hanson Cai	Fax / E-mail :	Hanson_cai@sgs.com
SGS File No.:	CN1US-065683	Date:	
		SGS Registration No.:	CN1US-065683

Buyer: Tivoli Audio, LLC

Agent: N/A

Supplier: Sunfield, TW

Manufacturer: Sunfield, Shen Zhen

Product description: Speakers and Grill kits

L/C Number: (x) Not Available

P.O. Number: (x) Not Available

Service performed: FRI Inspection Date: 05-Apr - 2005

Inspection Location: Sha Jing, Shen Zhen

REFERENCE SAMPLE PROVIDED:

By Princip. (For data measurement only)

**1.0 SUMMARY OF INSPECTION RESULT:**

Model No	Quantity for inspection	AQL applied	Sample size	Overall result
ST1 MKII	160	According to Client instruction are using ANSI/ASQC Z1.4-1993, Single sampling plans for normal inspection; AQL = Level I letter code Critical = Not allow Major = 0.65 Minor = 1.5	20 MAJ. 8 MIN.	Conformed
ST3 MKII	430		20 for maj./ 32 for minor	Conformed

Note: Inspection result are defined as "Conformed" "Not conformed" "Not applicable" and "Subject to Client's evaluation"

**FOLLOW UP ACTIONS: (as applicable)**☐ Inspection certificate will be issued☐ Supplier advised shipment scheduled for \_\_\_\_\_☐ Manufacturer / supplier commented on inspection result as follow: \_\_\_\_\_☐ Please instruct regarding issuance of inspection certificate.☐ We sent you defective samples by \_\_\_\_\_ AWB. No.: \_\_\_\_\_ on \_\_\_\_\_ Please advise your evaluation.Page 1 of 4  
CN-D-OPG-

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Disputations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.



19-AUG-2005 14:31 FROM SUNFIELD.COM.CN

TO 0088672240520

P.16/23

**SGS**☐ We recommend the following corrective action \_\_\_\_\_

Additional SGS service \_\_\_\_\_ results due by \_\_\_\_\_

**2.0 SUMMARY OF INSPECTION CONTENTS**

Model No	Style / Material / Color	Workmanship / Visual / Function	Packing	Marking / label	Data measurement
ST1 MKII	Conformed	Pass AQL	Conformed	Conformed	Actual Finding
ST3 MKII	Conformed	Pass AQL	Conformed	Conformed	Actual Finding

**3.0 WORKMANSHIP APPEARANCE / FUNCTION INSPECTION FINDINGS:**

(As according to Client's instruction "Critical and Major defect" are not allowed!  
And "Minor defect" are just for repair and improvement mainly!)

Model No	Defect description	Critical	Major	Minor
ST1	NO DEFECT WAS FOUND.	0	0	0
ST3	DIRTY MARK ON CABINET (S11739)	0	0	1

**4.0 PACKING**

Model No	Export packing	Individual packing
ST1 MKII	2 ply corrugated carton and sealed by gummed tapes	Each speaker protected with polybag and foam, then packed into carton together with accessories bag (3pcs spikes, 2pcs plastic foot, 3pcs rubber caps and 4pcs black screw), User's guide and Warranty card.
ST3 MKII	2 ply corrugated carton and sealed by gummed tapes	Each speaker protected with polybag and foam, then packed into carton together with 2pcs plastic feet and accessories bag (3pcs spikes, 3pcs rubber caps and 4pcs black screw), User's guide, Information sheet and Warranty card.

**5.0 MARKING / LABELING**

Model No	On Export carton
ST1 MKII	<p>1). Shipping mark</p> <p style="text-align: center;">Sapphire™ ST1 MKII High Performance Three-way Tower Speaker</p> <p>2). Side mark</p> <p><b>HANDLE WITH CARE</b> Designed and Engineered by Cary Christie And Tom DeVesto Exclusive 1Sapphire Polcell Dome Teeter 5.25" Aluminum Cone Midrange</p>

Page 2 of 4  
CN-D-025

This report is issued by the Company under the General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees of commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

19-AUG-2005 14:32 FROM SUNFIELD.COM.CN

TO 0088672240520

P.17/23

**SGS**

8" Side-firing Woofer  
Magnetically Shielded  
Bi-Wirable  
Bass Reflex Design  
Black Glass Top  
*Grilles Included.*

Quantity:  
One Right Speaker  
Premium Black Ash Vinyl  
One left Speaker  
Premium Black Ash Vinyl

Shipping:  
Wt: 52.7 lb  
Vol: 5.1 cu ft

**Sapphire™**  
RED HOT Blue!  
One Broadway, Suite 600  
Cambridge, Massachusetts 02142 USA  
[www.SapphireAudio.com](http://www.SapphireAudio.com)  
Sapphire and the Sapphire logo are trademarks of Sapphire audio.  
**MADE IN CHINA**

**ST3 MKII**1). Shipping mark

**Sapphire™**  
**ST3 MKII**  
High Performance Three-way Tower Speaker

2). Side mark**HANDLE WITH CARE**

Designed and Engineered by Cary Christie  
And Tom DeVesto  
Exclusive 1" Sapphire Polycell Dome Teeter  
2X5.25" Aluminum Cone Midrange  
2x8" Side-firing Woofer cone Woofers  
Magnetically Shielded  
Bi-Wirable  
Bass Reflex Design  
Black Glass Top  
Grilles Included

Quantity:  
One Right Speaker  
Premium Black Ash Vinyl  
One left Speaker  
Premium Black Ash Vinyl

Shipping:  
Wt: 71.6 lb  
Vol: 7.3 cu ft

**Sapphire™**  
RED HOT Blue!

Page 3 of 4  
CN-D-OPS

This report is issued by the Company under its General Conditions for Importation and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees of commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

19-AUG-2005 14:32 FROM SUNFIELD.COM.CN

TO 0088672240520

P.18/23

**SGS**

One Broadway, Suite 600  
 Cambridge, Massachusetts 02142 USA  
[www.SapphireAudio.com](http://www.SapphireAudio.com)  
 Sapphire and the Sapphire logo are trademarks of Sapphire audio. MADE IN CHINA

**6.0 DATA MEASUREMENT**

Model No	Data measurement
ST1 MKII	1). AC Impedance curve found acceptable except defects shown in AQL. 2). Speaker polarity check found acceptable except defects shown in AQL. 3). Buzz & Rattle check found acceptable except defects shown in AQL. 4). 1 pc rubber foot for "left mark test" found acceptable. 5). 3 pcs samples for actual installation check found acceptable.
ST3 MKII	1). AC Impedance curve found acceptable except defects shown in AQL. 2). Speaker polarity check found acceptable except defects shown in AQL. 3). Buzz & Rattle check found acceptable except defects shown in AQL. 4). 1 pc rubber foot for "left mark test" found acceptable. 5). 3 pcs samples for actual installation check found acceptable.

**7.0 PROBLEM REMARKS / INFORMATIVE REMARKS**

Model No	Problem remark / Informative remark
	1 UPC label stuck on export carton. 2 Rating label stuck on rear cabinet. 3 Serial number label stuck on unit and export carton.

19-AUG-2005 14:41 FROM SUNFIELD.COM.CN

TO 0088672240520

P.02/13

**SGS**

2/F Qaslar Building, Zhongkang Road, Shangmeilin, Shenzhen, China

Tel.: (86 755) 83114358

Fax: (86 755) 83114354/ 83103184

**Inspection Report**

Report Ref. No.: SZXWT00117795

To :	Sapphire Audio, LLC	Fax / E-mail :	
Att :	Tom Devesto		
Cc :	Sunfield Shenzhen	Fax / E-mail :	
Att :	Peter Peng		
From :	Hanson Cai	Fax / E-mail :	Hanson_cai@sgs.com
SGS File No.:	CN1US-075528	Date: 24/03/05	SGS Registration No.: CN1US-075528

Buyer : Sapphire Audio  
 Agent : N/A  
 Supplier : Sunfield, TW  
 Manufacturer : Sunfield speaker box (Shen Zhen) Co. Ltd.  
 Product description : Speakers

L/C Number : (x) Not Available  
 P.O. Number : (x) Not Available

Service performed : FRJ Inspection Date : 24-Mar-2005  
 Inspection Location : Sha Jing, Shen Zhen

REFERENCE SAMPLE PROVIDED : By Principal ( For data measurement only )

**1.0 SUMMARY OF INSPECTION RESULT :**

Model No	Quantity for inspection	AQL applied	Sample size	Overall result
SS	20 pcs	According to Client instruction are using ANSI/ASQC Z1.4-2003, Single sampling plans for normal inspection ;	20/8(M/N)	Subject to Client's evaluation
SC MKII	12 pcs		20/8(M/N)	Subject to Client's evaluation
SBL	20 pcs	AQL = Level I letter code Critical = Not allow Major = 0.65 Minor = 1.5	20/8(M/N)	Subject to Client's evaluation
ST3 MKII	6 pcs		20/8(M/N)	Subject to Client's evaluation

Note : Inspection result are defined as "Conformed" "Not conformed" "Not applicable" and "Subject to Client's evaluation"

**FOLLOW UP ACTIONS : ( as applicable )**

Inspection certificate will be issued

Supplier advised shipment scheduled for \_\_\_\_\_

Manufacturer / supplier commented on inspection result as follow : \_\_\_\_\_

Please instruct regarding issuance of inspection certificate.

Page 1 of 5  
CN-D-QPS.

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging of their liabilities under the Contract of Sale. Signatures to this company are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

19-AUG-2005 14:42 FROM SUNFIELD.COM.CN

TO 0088672240520

P.03/13

**SGS**

We sent you defective samples by \_\_\_\_\_ AWB. No.: \_\_\_\_\_ on \_\_\_\_\_ Please advise your evaluation.

We recommend the following corrective action: \_\_\_\_\_

Additional SGS service \_\_\_\_\_ results due by \_\_\_\_\_

**2.0 SUMMARY OF INSPECTION CONTENTS**

Model No	Style / Material / Color	Workmanship / Visual / Function	Packing	Marking / label	Data measurement
SS	Conformed	Pass AQL	Conformed	Conformed	Actual Finding
SC MKII	Conformed	Pass AQL	Conformed	Conformed	Actual Finding
SBL	Conformed	Pass AQL	Conformed	Conformed	Actual Finding
ST3 MKII	Conformed	Pass AQL	Conformed	Conformed	Actual Finding

**3.0 WORKMANSHIP APPEARANCE / FUNCTION INSPECTION FINDINGS:**

( As according to Client's instruction "Critical and Major defect" are not allow / And "Minor defect" are just for repair and improvement mainly! )

Model No	Defect description	Critical	Major	Minor
SS	No defect was found	0	0	0
SC MKII	No defect was found	0	0	0
SBL	No defect was found	0	0	0
ST3 MKII	No defect was found	0	0	0

**4.0 PACKING**

Model No	Export packing	Individual packing
SS	2 ply corrugated carton and sealed by gummed tapes	Two unit protected with polybag and foam, then packed into carton together with accessories bag ( 1 pc copper foot, 6 pcs rubber foot), User's guide and Warranty card.
SC MKII	2 ply corrugated carton and sealed by gummed tapes	Each speaker protected with polybag and foam, then packed into carton together with 1 accessories bag ( 6 pcs rubber foot), User's guide and Warranty card.
SBL	2 ply corrugated carton and sealed by gummed tapes	Two speakers protected with polybag and foam, then packed into carton together with 1 accessories bag ( 8 pcs rubber foot), User's guide and Warranty card.
ST3 MKII	2 ply corrugated carton and sealed by gummed tapes	Each unit was protected with poly bag and poly foam, then packed into carton together with accessories bag (3pcs copper foot, 3pcs rubber foot, 4pcs black screw, user's guide and warranty card.)

Page 2 of 6  
CN-D-OPS-

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Statements in the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence, and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

19-AUG-2005 14:42 FROM SUNFIELD.COM.CN

TO 0088672240520

P.04/13

**SGS****5.0 MARKING / LABELING**

Model No	On Export carton
SS	<p><u>1). Shipping mark</u></p> <p>Sapphire™ <b>SS</b> Two-way High Performance Diffuse Surround Speakers</p> <p>Quantity: Two</p> <p><u>2). Side mark</u></p> <p><b>HANDLE WITH CARE</b> Designed and Engineered by Cary Christie And Tom DeVesto Exclusive 1" Polycell Dome Sapphire Tweeter 5.25" Aluminum Cone Midrange/ Woofer</p> <p>Quantity: Two Speakers Premium Black Ash Vinyl</p> <p>Shipping: Wt: 40.3 lb Vol: 2.6 cu ft</p> <p>Sapphire™ RED HOT Blue! One Broadway, Suite 600 Cambridge, Massachusetts 02142 USA <a href="http://www.SapphireAudio.com">www.SapphireAudio.com</a> Sapphire and the Sapphire logo are trademarks of Sapphire audio. <b>MADE IN CHINA</b></p>
SC MKII	<p><u>1). Shipping mark</u></p> <p>Sapphire™ <b>SC MKII</b> High Performance Two-way Center Channel</p> <p>Quantity: One</p> <p><u>2). Side mark</u></p> <p><b>HANDLE WITH CARE</b> Designed and Engineered by Cary Christie and Tom DeVesto Exclusive 1" Sapphire™ Polycell Dome Tweeters 2x5.25" Aluminum Cone Midrange/ Woofer Magnetically Shielded Bass reflex Design Adjustable Center Foot Grilla included</p> <p>Quantity:</p>

Page 3 of 6  
CN-D-OPS-

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

19-AUG-2005 14:42 FROM SUNFIELD.COM.CN

TO 0088672240520

P.05/13

**SGS**

	<p>One Speaker Premium Black Ash Vinyl Shipping: Wt: 24.6 lb Vol: 2.1cu ft</p> <p><b>Sapphire™</b> RED HOT Blue! One Broadway, Suite 600 Cambridge, Massachusetts 02142 USA <a href="http://www.SapphireAudio.com">www.SapphireAudio.com</a> Sapphire and the Sapphire logo are trademarks of Sapphire audio. <b>MADE IN CHINA</b></p>
<b>SBL</b>	<p><u>1). Shipping mark</u></p> <p style="text-align: center;">Sapphire™ <b>SBL</b> Two-way High Performance Bookshelf Speakers</p> <p style="text-align: center;">Quantity: Two</p> <p><u>2). Side mark</u></p> <p><b>HANDLE WITH CARE</b> Designed and Engineered by Cary Christie And Tom DeVesta Exclusive 1" Polycell Dome Sapphire Tweeter Hand- Lacquered Front baffle magnetically Shielded 6.5" aluminum cone midrange/ woofer Bass Reflex Design</p> <p>Quantity: Two Speakers Premium Black Ash Vinyl</p> <p>Shipping: Wt: 34.3 lb Vol: 3.1 cu ft</p> <p><b>Sapphire™</b> RED HOT Blue! One Broadway, Suite 600 Cambridge, Massachusetts 02142 USA <a href="http://www.SapphireAudio.com">www.SapphireAudio.com</a> Sapphire and the Sapphire logo are trademarks of Sapphire audio. <b>MADE IN CHINA</b></p>
<b>ST3 MKII</b>	<p><u>1). Shipping mark</u></p> <p style="text-align: center;">Sapphire™ <b>ST3 MKII</b> High performance three-way Tower Speaker</p> <p><u>2). Side mark</u></p> <p><b>HANDLE WITH CARE</b></p>

Page 1 of 5  
ON-D-ORS

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Disputations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the loss or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.



19-AUG-2005 14:43 FROM SUNFIELD.COM.CN

TO 0088672240520

P.06/13

**SGS**

Designed and Engineered by Cary Christie  
and Tom DeVesto  
Exclusive 1" Sapphire Polycell Dome Tweeter  
2x5.25" Aluminum Cone Midranges  
2x8" side-firing woofer cone Woofers  
Magnetically Shielded  
BI-Wirable  
Bass Reflex Design  
Black Glass Top  
Grilles Included  
MADE IN CHINA

Quantity:  
One right Speaker  
Premium Black Ash Vinyl

One left Speaker  
Premium Black Ash Vinyl

Shipping:  
Wt: 71.6 lb  
Vol: 7.3 cu ft

**Sapphire™**  
RED HOT Blue!  
One Broadway, Suite 600  
Cambridge, Massachusetts 02142 USA  
[www.SapphireAudio.com](http://www.SapphireAudio.com)  
Sapphire and the Sapphire logo are trademarks of Sapphire audio.

**6.0 DATA MEASUREMENT**

Model No	Data measurement
SS	1). AC Impedance curve found acceptable except defects shown in AQL. 2). Speaker polarity check found acceptable except defects shown in AQL.. 3). Buzz & Rattle check found acceptable except defects shown in AQL.. 4). 3pcs samples for actual installation check found acceptable. 5). 1 pc rubber foot for "left mark test" found acceptable.
SC MKII	1). AC Impedance curve found acceptable except defects shown in AQL.. 2). Speaker polarity check found acceptable except defects shown in AQL.. 3). Buzz & Rattle check found acceptable except defects shown in AQL.. 4). 1 pc rubber foot for "left mark test" found acceptable.
SBL	1). AC Impedance curve found acceptable except defects shown in AQL.. 2). Speaker polarity check found acceptable except defects shown in AQL.. 3). Buzz & Rattle check found acceptable except defects shown in AQL.. 4). 1 pc rubber foot for "left mark test" found acceptable.
ST3 MKII	1). AC Impedance curve found acceptable except defects shown in AQL.. 2). Speaker polarity check found acceptable except defects shown in AQL.. 3). Buzz & Rattle check found acceptable except defects shown in AQL.. 4). 3pcs samples for actual installation check found acceptable.

**7.0 PROBLEM REMARKS / INFORMATIVE REMARKS**

Page 5 of 6  
CN-D-OPS-

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

19-AUG-2005 14:43 FROM SUNFIELD.COM.CN

TO 0088672240520

P.07/13

**SGS**

Model No	Problem remark / Informative remark
	1 UPC label stuck on export carton.
	2 Rating label stuck on rear cabinet.
	3 Serial number label stuck on unit and export carton.

Page 6 of 8  
CN-D-OPS-

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be returned by the Company for more than three months.

19-AUG-2005 14:43 FROM SUNFIELD.COM.CN

TO 0088672240520

P.08/13

**SGS**

2/F Oaster Building, Zhongkang Road, Shangmeilin, Shenzhen, China

Tele.: (86 755) 83114358

Fax: (86 755) 83114354/ 83103194

**Inspection Report**

Report Ref. No.: SZXWT00117213

To :	Sapphire Audio, LLC	Fax / E-mail :	
Att :	Tom Devesto		
Cc :	Sunfield Shenzhen	Fax / E-mail :	
Att :	Peter Peng		
From :	Hanson Cai	Fax / E-mail :	Hanson_cai@sgs.com
SGS File No.:	CN1US-075023	Date:	17/03/05
		SGS Registration No.:	CN1US-075023

Buyer : Sapphire Audio LLC

Agent : N/A

Supplier : Sunfield, TW

Manufacturer : Sunfield, Shen Zhen

Product description: Speakers

L/C Number : (x) Not Available

P.O. Number : (x) Not Available

Service performed : FRI Inspection Date : 17-Mar-2005

Inspection Location : Sha Jing, Shen Zhen

REFERENCE SAMPLE PROVIDED :

By Principal ( For data measurement only )

**1.0 SUMMARY OF INSPECTION RESULT :**

Model No	Quantity for inspection	AQL applied	Sample size	Overall result
SBS	<del>32</del> cs	According to Client Instruction are using ANSI/ASQC Z1.4-1993, Single sampling plans for normal inspection :	32	Not conformed
SC	<del>112</del> cs		32	Subject to Client's evaluation
SB	<del>88</del> cs		<del>20</del>	Subject to Client's evaluation
ST3	<del>120</del> cs	AQL = Level I letter code Critical = Not allow Major = 0.65 Minor = 1.5	<del>20</del>	Subject to Client's evaluation

**Note :** Inspection result are defined as "Conformed" "Not conformed" "Not applicable" and "Subject to Client's evaluation"

**FOLLOW UP ACTIONS : ( as applicable )**

Inspection certificate will be issued

Supplier advised shipment scheduled for \_\_\_\_\_

Manufacturer / supplier commented on inspection result as follow : \_\_\_\_\_

Please instruct regarding issuance of inspection certificate.

Page 1 of 5  
CN-D-OPS-

This report is issued by the Company under its General Conditions for Inspection and Testing Services (copy available upon request). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.